



*Status of Sensors:*

## **Sensors and bump-bonding**

Jianguo Zhang

*Deutsches Elektronen-Synchrotron (DESY)*

# Content



- **Status of sensor and bump-bonding**
- **Some observed issues**
- **Summary**

- Sensors:
  - 2 batches received from Sintef

	Batch-1	Batch-2	Sum
Nr. wafers* received	20	25	45
Nr. cut wafers	2	2	4
Nr. processed** wafers	14	0	14
Nr. remaining wafers	4	23	27

\* 1 wafer → 2 sensors

\*\* processed wafer → UBM, bump deposition (Dectris) & cut


- Bump-bonding:
  - new bonding machine
  - effort made to make bonding properly

# Some observed issues




- Issues observed in UBM & bump deposition processes (by Dectris):
    - metal adhesion
    - scratches
    - particles on/inside passivation
- } → influence on imaging quality


metal layer problem



scratches





particles



Similar observations through visual inspection at UHH!

# Reminder: Visual inspection


- Visual inspection for pixels and guard-ring structure of ~ 10 wafers
  - problems observed for passivation and metalisation



- Judged as bad sensor by Sintef from I-V measurement; actual problems observed through visual inspection at HH
- Information stored (12k images/sensor) → “trace back” in case problem

**Metal adhesion:**

- in GRs: early breakdown (2 sensors)
- in pixels: loss spatial resolution (2/65536 pixels)



# Bad pixels



- Bad pixels (= sensor pixels + ASIC pixels + unbonded bumps)



- flat-field image
- dark-field corrected
- ADC gain corrected

~ 0.6% bad pixels (estimate):

- <0.1% from ASICs
- ~0.2% from unbonded bumps:
  - \* 0.08% due to bonding
  - \* 0.12% due to size of indium ball
- ~0.3% from sensor:
  - \* <0.2% hot pixel
  - \* others

“Trace back” sensor inspection:

- metal adhesion: 1
- scratch: 0
- **particles: ~ 604**



“Contaminated” sensor (more sticky particles)! → check other modules!

# Bad pixels



- Bad pixels (= sensor pixels + ASIC pixels + unbonded bumps)



- flat-field image
- dark-field corrected
- ADC gain corrected

~ 0.6% bad pixels (estimate):

- <0.1% from ASICs
- ~0.2% from unbonded bumps:
  - \* 0.08% due to bonding
  - \* 0.12% due to size of indium ball
- ~0.3% from sensor:
  - \* <0.2% hot pixel
  - \* others

“Trace back” sensor inspection:

- metal adhesion: 1
- scratch: 0
- **particles: ~ 604**



“Contaminated” sensor (more sticky particles)! → check other modules!

# Summary




- **Issues observed for sensors (by Dectris & previously@UHH)**
- **Measurement for sensor after bump-bonding:**
  - bad pixel: ~ 0.6% for a “contaminated” sensor
    - ~ 0.4% non-working pixels
    - ~ 0.2% hot (noisy) pixels
- **Following work and plan:**
  - check results for “non-contaminated” sensors
  - quick inspection on sensor before bump-bonding
  - optimize bump-bonding process and improve bonding yield
  - discuss the issue with sensor vendor

Be aware: statistic is 1!



Spin coating (lift-off-resist) and printing of photoresist







Photoresist stripping and wet etching

# Sensor flatness




- Flatness measurement
  - fit to a plane for individual sensor:
  - radius of curvature:  $\sim 100$  m
  - max. force on a bond pad (0.01 – 0.1 mN)  
(bonding force: , de-bonding: )

Measurement & Fit for Sensor-1



# Electric field



# Weighting potential



2D simulation

Bonded pixel    Unbonded pixel    Bonded pixel

